

Initial Application

- Start with a clean floor. Blockade areas to be cleaned. Floors will be slippery until dry.
- Apply undiluted with a microfiber mop (can be sprayed directly on floor and spread with microfiber mop.)
- Wait 4-6 minutes for drying and then repeat application.

Ongoing Maintenance

Automatic Scrubbing Machines:

- Add 4 oz. per gallon of Tuff-Shine to warm water.
- Scrub floor with Tuff Shine solution.
- Trail mop excessive wet areas behind scrubber.
- Do not rinse floor. Let dry completely before being exposed to normal traffic.

Mop & Bucket Cleaning:

- Add 2 oz. per gallon of Tuff- Shine to warm water.
- Mop floor clean with Tuff-Shine solution.
- Pick up soil and excess cleaner with a tightly wrung-out mop.
- Do not rinse floor. Let dry completely before being exposed to normal traffic.

** For increased shine, buff the Tuff- Shine coated floor with a white polishing pad or soft buffing pad 24 hours after application. **



1.888.604.3625