



TUFF SHINE

DIRECTIONS: Dust mop or Sweep. Blockade areas to be cleaned. Floors will be slippery until dry.

Automatic Scrubbing Machines: Add 4 oz. per gallon of **TUFF-SHINE** emulsion to warm water. Scrub floor with product. Trail mop excessive wet areas behind scrubber. Do not rinse floor. Let floor dry completely.

Mop and Bucket Cleaning: Add 2 oz. per gallon of **TUFF-SHINE** to warm water. Mop floor clean. Pick up soil and excess cleaner with a tightly wrung-out cleaning mop. Do not rinse floor. Let floor dry completely.

TUFF-SHINE can be applied undiluted with multiple coats for increased shine. Allow approximately 20 minutes of drying time between coats. For increased shine, buff the clean Nu-Wax coated floor with a 175 rpm machine with a white or buffing pad.

CAUTION: Keep out of reach of children. Avoid contact with eyes skin and clothing. Do not take internally. It is recommended that users wear protective gloves and eye protection when handling this and any cleaning product.

FIRST AID: FOR SKIN CONTACT: Remove affected clothing and wash all exposed skin areas with mild soap and water, followed by warm water rinse. FOR EYE CONTACT: Rinse immediately with plenty of water. Obtain medical attention if pain, blinking or redness persists. FOR INHALATION: Assure fresh air breathing. Allow victim to rest. FOR INGESTION: Rinse mouth. DO NOT induce vomiting. Obtain emergency medical attention. Never give anything by mouth to an unconscious person.

INGREDIENTS (CAS#): Water (7732-18-5), Diethylene Glycol Monoethyl Ether (111-90-0), Acrylic Copolymer (58479-13-3), Alcohol Ethoxylates (68439-46-3).

ULTRA SHIELD PRODUCTS CORP.

1.888.604.3625