



Ultra Shield Burnishing Formula

Instructions for Use

Spray Bottle Application



- Squeeze 1 ounce of Ultra Shield into measuring chamber
- Pour 1 ounce into an empty spray bottle
- Add water to spray bottle
- Set trigger sprayer to "stream"
- Spray Ultra Shield on work area and begin burnishing right away.



Mop-On Application



- Squeeze 2 ounces of Ultra Shield into measuring chamber for every gallon of water in the mop bucket.
(Example: 2 gallons of water = 4 ounces of Ultra Shield.)
- Mix product in the bucket with your mop.
- Ring out the mop head well.
- Mop diluted product very thinly on work area and begin burnishing.

**DO NOT ADD MORE PRODUCT THAN INSTRUCTED
DO NOT OVER SOAK THE FLOOR WHEN APPLYING**



Recommended Pads

- For best results we recommend any medium to aggressive hair pad.
- No White or Red polishing pads.

